

ATLANTIC PILOTAGE AUTHORITY OHS SYSTEM

RISK: PB001

RISK ANALYSIS

Task, Tool, Equipment, People, Condition: Releasing Lines – Departing Dock

Location: Chebucto Pilot **Date:** September 30, 2016

Performed By: SD and HH **Manager(initial):** DL

Risk = likelihood x severity of loss resulting from exposure to hazards. Once the hazards are identified, rate the overall risk as either: H (High), M (Medium) or L (Low). Record the rating in the box in the top left corner. Higher risks require immediate attention and elevated controls.

Basic Steps and/or Conditions	Existing or Potential Hazards	Recommended Controls, Corrective Actions
Deckhand to position self on deck	Tripping/slipping hazards on deck Risk of Falling Overboard	Ensure working area is clean and ice free (during winter) Wear PFD Ensure launchmaster is aware of whereabouts on deck Wear appropriate PPE/Clothing for weather conditions
Deckhand to release lines	Vessel movement	Launchmaster to give signals when ready to move lines
	Risk of Nearby boaters/ jetskis/ kayakers/ debris	Check to ensure area around vessel is clear of obstruction or other boaters Launchmaster to keep vessel alongside until gets signal it is all clear